

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

UNIT T	YPE: (check al	I that apply	y to tl	his audit	with:	same Permi	t number)	
Lined MSWLF	LCID	YW		Transfer	X	Compost	SLAS	COUNTY: Yancey County
Closed MSWLF	HHW	White goods	X	Incin		T&P	FIRM	PERMIT NO.: 100-03T
CDLF	Tire T&P / Collection	Tire Monofill		Industrial Landfill		DEMO	SDTF	FILE TYPE: COMPLIANCE

Date of Audit: August 4, 2004.

Date of Last Audit: April 14, 2004.

Fac/Perm/Co ID # Date Doc ID# 100-03T 6 120,08 DIN 4948

FACILITY NAME AND ADDRESS:

Yancey County Transfer Station Booneford Rd, Bandana, NC. 28714

FACILITY CONTACT NAME AND PHONE NUMBER:

Tom Tipton, Public Works Director 828-678-9180

FACILITY CONTACT ADDRESS (IF DIFFERENT):

Court House, Room 13, Burnsville, NC. 28714

AUDIT PARTICIPANTS:

Albert A. Hetzell WMS, Solid Waste Section, DENR Tom Tipton, Public Works Director

STATUS OF PERMIT:

Active - Review Date September 7, 2005

PURPOSE OF AUDIT:

Partial Audit

NOTICE OF VIOLATION(S) (citation and explanation): None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$5,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. If the violation(s) noted here continue, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

STATUS OF PAST NOTED VIOLATIONS (List all noted last audit): 15A North Carolina Administrative Code

13B .0402 (1) states: Operational plan shall be approved and followed as specified in the permit. Yancey Co was in Violation of 13B .0402 (1) Permit operational condition 7b, Permit operational condition 7c.

Yancey County has corrected the violations by covering the trailers which have waste in them at the end of the day and is cleaning the trailer loading bay.

Violation Corrected

OTHER COMMENTS / SUGGESTIONS:

- 1.) Tipping floor empty of waste.
- 2.) Metal trailer full. Some fuel/gas tanks are accumulating.
- 3.) Metal loading area needs better cleaning
- 4.) Weather sunny dry.



FACILITY COMPLIANCE AUDIT REPORT Division of Waste Management Solid Waste Section

Page 2 of 2

Please contact me if you have any questions or concerns regarding this audit report.

What Co. 1965 Phone: 828-296-4701.

Regional Representative/WMS

Mailed on : August 06, 2004 hand delivery X US Mail X Certified No. [_]

Distribution: original signed copy to facility - signed copy to compliance officer - email or copy to supervisor

CC: Mark Poindexter, Field Operations Branch Head Brent Rockett, Western District Supervisor